ITEM PART# QTY. **DESCRIPTION** 521847.13 **DECK STIFFENER PLATE** 2 304109 CARR. BOLT- 7/16 X 1.25 NC GR5 PL 4 3 301303 LOCK WASHER- 7/16 PL 4 4 301103 FLAT WASHER- 7/16 PL 4 5 305603 HEX NUT - 7/16NC GR5 PL 4




FIGURE 2. PLATE INSTALLATION

PROCEDURE:

- 1. BEFORE ANY WORK IS COMPLETED ON THE MACHINE ENSURE THAT THE WINGS ARE DOWN AND THE MACHINE IS ON A SAFE AND FLAT SURFACE. DISCONNECT TRACTOR FROM MOWER BEFORE WELDING. SEE OPERATOR'S MANUAL FOR FURTHER INSTRUCTIONS.
- 2. REMOVE DECK SHIELDING AND BELTS. THEN REMOVE GEAR BOX, PULLEY, AND THE MOUNTING PLATE. SEE FIGURE 1.
- 3. PLACE PART 521847.13 DECK STIFFENER PLATE OVER SPINDLE AND ENSURE IT IS CENTERED AND THE HOLES ARE LINED UP. USE THE CARRIAGE BOLTS TO LINE UP THE HOLES. SEE FIGURE 2.
- 4. STITCH WELD IN THE PLATE. SEE FIGURE 3 DETAIL A FOR WELDING INSTRUCTIONS.
- 5. REINSTALL THE GEAR BOX AND BELTS AND TENSION BELTS PROPERLY. SEE OPERATOR'S MANUAL.
- 6. REINSTALL DECK SHIELDING.

Α	21016	FIRST RELEASE	2021-11-04	IDB
REV.	DCN	DESCRIPTION	DATE	BY
REVISIONS				





FIGURE 3. WELD **DETAIL A SCALE 1:6**



THREE PLACE DECIMAL ± 0.005

2

521847.13 - DECK STIFFENER PLATE

PROGRESSIVE TURF EQUIPMENT INC IS

SCALE: 1:16 WEIGHT: 629.266 SHEET 1 OF 1

REV

-3/16" FILLET 1-1/2" STITCH | c

WELD ON THREE SIDES AND CENTER IF

POSSIBLE